

GOVERNMENT OF ANDHRA PRADESH  
ROADS AND BUILDINGS DEPARTMENT

From  
Sri G.Chalapathi, B.Tech.,  
Deputy Executive Engineer,  
(R&B) Buildings Sub-division,  
K U R N O O L.

To  
The Principal,  
St.Joseph's English School,  
Building No.41/144-1 & 41/195  
N.R.Peta,  
KURNOOL.

Letter.No.421/SA/SSC/2025-26

Dated: 05-02-2026

Sir,

Sub:- (R&B) Buildings Sub-division, Kurnool – School Building Structural Soundness Certificates of St.Joseph's English School, Building .41/144-1, 41/195 N.R.Peta, Kurnool in Kurnool district - Issued – Regarding.

Ref:- 1.Lr No. Nil, dated: 26.01.2026 of the St.Joseph's English School, N.R.Peta, Kurnool.

2.Challan No.91334880982025, dated: 26.01.2026.

<<<<>>>>

With reference to your letter 1<sup>st</sup> cited, it is to inform that, I have inspected the St.Joseph's English School, Building 41/144-1, 41/195, N.R.Peta, Kurnool in Kurnool district on 04.02.2026 and reported that the school building is Structurally Sound and it is fit to run. The soundness certificate is valid for 2026-2027.

The Structural Soundness Certificate as requested by you is herewith enclosed for taking further necessary action.

Yours faithfully,



Deputy Executive Engineer,  
(R&B) Buildings Sub-division: Kurnool.

Encls:-  
Structural Soundness Certificates.

## **Structural Soundness Certificate**

This is certifying that, I have inspected the St.Joseph's English School, D.No.41/144-1 and 41/195, N.R Peta, Kurnool in Kurnool district on 04.02.2026 and found it is to be safe and structurally sound. This certificate is valid for the year 2026-2027.

Place: Kurnool

Dated: 04.02.2026

Yours faithfully,



Deputy Executive Engineer,  
(R&B) Buildings Sub-division: Kurnool.